
## **WS 9130**

## Chipboard screws countersunk head with TX and full thread



dk	6	7	8	9	10	12
k ☀	1,50 TX 10	1,75 TX 10	2,00 TX 20	2,25 TX 20	2,50 TX 25	3,00 TX 25
Length /Ø	3	3,5	4	4,5	5	6
10	<b>A</b> •					
13	<b>A</b> •	<b>A</b> •	<b>A</b> •			
16	<b>A</b> •	<b>A</b> •	<b>A</b> •			
20	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	
25	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	
30	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
35	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
40		<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
45			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
50			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
55			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
60			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
70			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
80			<b>A</b> •	<b>A</b> •	<b>A</b> •	<b>A</b> •
90					<b>A</b> •	<b>A</b> •
100					<b>A</b> •	<b>A</b> •
SU	1000	1000	500	500 ≥ 40 200	200 ≥ 70 100	200 ≥ 70 100

■ A1 / ▲ A2 / ● A4 | SU: Sales unit | All measurements in mm | Other dimensions on request. Example item no. 9130-2-6X40 WS 9130 - A2 -  $\emptyset$  6mm - I = 40mm